



X-TYPE

DATE 11/02
Amended 03/03

XT412-S931

SERVICE

TECHNICAL BULLETIN

A/C System Inoperative –
Reprogram ECM –
Service Action S931

MODEL 2003 MY
X-TYPE
VIN C86115-D14654

Remove and destroy Bulletin XT412-S931 dated 11/02.
Replace with this Bulletin.
This Service Action is superseded by S937.

Issue:

A revised software level was introduced in production on 2003 MY X-TYPE vehicles from VIN C86115. This software level has created a situation where the air conditioning system will not operate if certain vehicle operating conditions have not been met. New ECM software that addresses this concern is now available.

Action:

Refer to Technical Bulletin XT303-S937 for Service Action S937.